



09,658,193

FW CGC

PATENT
Customer No. 22,852
Attorney Docket No. 08038.0032

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re U.S. Patent No.: 6,838,370 B1)
Inventors: Takayuki NIUYA et al.)
Issue Date.: January 4, 2005)
For: METHOD OF MANUFACTURING)
SEMICONDUCTOR DEVICE AND)
MANUFACTURING APPARATUS)

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Sir:

REQUEST FOR CERTIFICATE OF CORRECTION

Pursuant to 35 U.S.C. § 254, and 37 C.F.R. § 1.322, this is a request for a Certificate of Correction in the above-identified patent. Two (2) copies of PTO Form 1050 are appended. The complete Certificate of Correction involves (1) page.

The mistakes identified in the appended Form PTO 1050 occurred through the fault of the Patent Office, as clearly disclosed by the records of the application which matured into this patent.

Issuance of the Certificate of Correction containing the correction is earnestly requested.

Please charge any required fees not included herewith to our Deposit Account

No. 06-0916.

Respectfully submitted,

FINNEGAN, HENDERSON, FARABOW,
GARRETT & DUNNER, L.L.P.

Dated: March 22, 2005

By: 
Michael W. Kim
Reg. No. 51,880

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. US 6,838,370 B1
DATED: January 4, 2005
INVENTORS: Takayuki NIUYA et al.

It is hereby certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In claim 1, column 9, line 4, "buying" should read --burying--.

In claim 1, column 9, line 19, "film," should read --film;--.

MAILING ADDRESS OF SENDER

Finnegan, Henderson, Farabow,
Garrett & Dunner, L.L.P.
901 New York Avenue, NY
Washington, D.C. 20001-4415

Patent No. US 6,838,370 B1

No. of additional copies
@ .30¢ per page
